

****IMPORTANT NOTICE****

Ensure that the front panel INPUT setting is set correctly to match the input jack being used.

An incorrect setting will not damage the Atlas, but will result in severe distortion and other signal degradation.